


# detector lamps and pump spares

## Pump spares

### Beckman



## Ordering information

| Cat. No.                        | Pump  | Manufacturer's P/N |
|---------------------------------|---|--------------------|
| <b>Piston seals</b>             |   |                    |
| SEA-420                         | 100A/110/108  | 887138             |
| <b>SBA-220G</b>                 | <b>100A/110(Gold)</b>   |                    |
| SBA-420P                        | 100A/110 (Clear)-UPC  |                    |
| SBA-520                         | 112/114   | 236797             |
| SBA-620                         | 116/126   | 237162             |
| SBA-720                         | 105/110 (PREP)  | 887 139/240037     |
| <b>Sapphire pistons</b>         |   |                    |
| SBA-200                         | 100/1 01 /1 OOA   | 243044             |
| SBA-400                         | 110/110N112   | 243053             |
| SBA-414                         | 114/116/126   | 240714f236977      |
| <b>Check valves(and spares)</b> |   |                    |
| SBA-6001                        | 110 Inlet CV  | 240720f243054      |
| SBA-6002                        | 110 Outlet CV   | 240721             |
| SBA-3001                        | 100A/112/114/116/126 Inlet CV                                 | 243038/243039      |
| SBA-3002                        | 100A/112/114/116/126 Outlet CV                                | 24072 1/243040     |
| SBA-920                         | Washer Seal (inlet) 110                                       | 243711             |
| SBA-I 01                        | Ball & Seat (Inlet) 3/16" <b>110</b>                          | 243712             |
| SBA-995                         | Kel-F Washer (Pump Head) 110                                  | 243091             |
| SBA-700                         | Kel-F Washer (Inlet) 1/2/1/4                                  | 244187             |
| SBA-102                         | Ball & Seat (Inlet) 1/2/1/4 (1/8")                            | 243659             |
| SBA-950                         | Thick Kel-F Washer 1/2/1/4                                    | 243658             |
| SBA-800                         | Frit Filter (Outlet)  | 243067             |
| SBA-102                         | Ball & Seat (Outlet) (3mm)                                    | 243659             |
| SBA-900                         | Kel-F Washer (Outlet)   | 244187             |
| SBA-100                         | Ball & Seat (1/8")  |                    |
| SBA-410                         | Piston Guide  | 243045             |
| SBA-450                         | Piston Bushing (1/2)  | 236790             |
| SBA-456                         | Piston Guide Bushing  | 236790             |
| SBA-500                         | Seat Insertion Tool   | 243070             |
| SBA-713                         | <b>110</b> Piston Sleeve                                      | 243713             |
| SBA-714                         | 110 Graphite Bushing  | 243714             |
| <b>Cartridge check valves</b>   |   |                    |
| <b>SOT- 1134</b>                | Inlet Housing/112,114M,116,126                                | 239423             |
| SOT-I 135                       | Outlet Housing/110,112,114M,116,126                           | 240061             |
| SOT-1 047B                      | Double Ball/Seat Cartridge CV for 1134/1135                   |                    |
| SOT-I 136                       | Complete Inlet CV<br><b>(i. e. SOT- 1134+SOT- 1047B)</b>      |                    |
| SOT-1137                        | Complete Outlet CV<br><b>(i. e. SOT- 1135+SOT- 1047B)</b>     |                    |
| SOT-I 138                       | <b>Inlet Housing 010</b>                                      |                    |
| SOT-1017                        | <b>3/16" Cartridge CV for SOT- 1138</b>                       |                    |
| <b>SOT- 1139</b>                | Complete Inlet CV- 110<br><b>(i. e. SOT- 1134+SOT- 1047B)</b> |                    |

## Detector lamps

### Beckman

| Cat. No.              | Type      | Model                       | Manufacturer's P/N |
|-----------------------|-----------|-----------------------------|--------------------|
| <b>Detector lamps</b> |           |                             |                    |
| DAB-901               | Mercury   | <b>1508/153</b>             | <b>243073</b>      |
| DAB-905               | Deuterium | <b>155</b>                  | <b>22887153</b>    |
| DAB-907               | Tungsten  | <b>155</b>                  | <b>887154</b>      |
| DAB-902               | Mercury   | <b>160</b>                  | <b>235844</b>      |
| DAB-903               | Cadmium   | <b>160</b>                  | <b>235958</b>      |
| DAB-904               | Zinc      | <b>160</b>                  | <b>235959</b>      |
| DAB-909               | Deuterium | <b>163</b>                  | <b>22947029</b>    |
| DAB-906               | Deuterium | <b>1651167</b>              | <b>236920</b>      |
| DAB-91 3              | Deuterium | <b>tem Gold</b>             | <b>239372</b>      |
| DAB-91 4              | Deuterium | <b>2000 Electrophoresis</b> |                    |