


detector lamps and pump spares

Pump spares
LDC, Milton Roy, (TSP)



Ordering information

| Cat. No. | Description | Manufacturer's P/N |
|----------------------------------|----------------------------|--|
| Piston seals - all models | | |
| SLD-500 | Black Seal Replacement Kit | 801598 |
| SLD-220 | Black Seal Only | 206129-001 |
| SLD-220G | Gold Seal | 206156-001 |
| SLD-220P | Polyethylene Seal (UPC) | 206156-001 |
| SLD-500G | Gold Seal Replacement Kit | 801892-001 |
| SLD-420 | Black Extended Heel | |
| SLD-420G | Gold Extended Heel | |
| Sapphire pistons | | |
| SLD-200 | Piston | 801306 |
| Check valves (and spares) | | |
| SLD-3501 | Inlet CV | 802497001 |
| SLD-3502 | Outlet CV | 802497002 |
| SLD-100 | Ball & Seal | 923-6001-000 |
| SLD-900 | CV Rebuild Kit | 900517 |
| SLD-902 | Ring Neck Collar | 9024-I 3-000 |
| SLD-916 | Cross Head Spring | 91602-82-000 |
| SLD-4001 | CV Cartridge (VS pump) | 802311 |
| Cartridge check valves | | |
| SOT-1211 | All | Inlet Housing Only |
| SOT-1210 | All | Outlet Housing Only |
| SOT- 1047 | For use with SOT-121 1 | Double Ball/Seat CARTRIDGE and SOT-121 0 |
| SOT-1132 | All | Complete Inlet CV Assembly 09.00 (1211 + 1047) |
| SOT- 4133 | All | Complete Outlet CV Assembly |

Detector lamps
LDC, Milton Roy, (TSP)

| Cat. No. | Description | Detector Model | Manufacturer's P/N |
|-----------------------|-------------|-------------------------------------|--------------------|
| Detector lamps | | | |
| DLD-901 | Mercury | UV3 , 1203/Fluor 111 | 108036 |
| DLD-902 | Deuterium | Spectra 1 + 2 | 108035 |
| DLD-903 | Tungsten | Spectra 1 + 2 | 108028 |
| DLD-904 | Mercury | 1205, 1235,1309, 1520 | 108002 |
| DLD-902 | Deuterium | Spectra 3 + D 3100 Series (4000) | 900347 |
| DLD-905 | Zinc | Fluor 111 | 920-2300-10 |
| DLD-906 | Cadmium | Fluor 111 | |
| DLD-907 | Deuterium | 31 | |
| DLD-909 | Deuterium | LDC 4100 | |
| DLD-910 | Deuterium | 3000 | |